

| Engineering Bulletins | | | |
|------------------------------|-------------|---|--------------|
| Doc # | Date | Description | Rev # |
| EB13001 | 12/03/2013 | Procedural changes to installation of turbo | 1 |
| EB13002 | 11/11/2013 | Exhaust Manifold to Turbo Connection | 1 |
| EB13003 | 11/11/2013 | Radiator Cleaning Access | 1 |
| EB13004 | 24/04/2015 | Radiator Design Change | 2 |
| EB13005 | 11/11/2013 | Front Drive shaft loop | 1 |
| EB13006 | 11/11/2013 | Particulate filter housing | 1 |
| EB13007 | 19/11/2013 | Relief valve on MONEx Shutdown system | 1 |
| EB15001 | 09/01/2015 | Hydraulic return hose in Articulation | 1 |
| EB15002 | 03/09/2015 | Load frame Pins | 2 |
| EB15003 | 16/02/2015 | Sealing of Deutsch Connectors used on the MONEx System | 1 |
| EB15004 | 19/02/2015 | Caterpillar Electronic Injector Unit Trim Files | 1 |
| EB15005 | 16/04/2015 | Exhaust Back Pressure Sensor | 2 |
| EB15006 | 14/05/2015 | Start Valve | 1 |
| EB15007 | 10/04/2014 | Hydraulic Tank Level Sensor Pneumatic Tubing | 1 |
| EB15008 | 19/09/2015 | Water Pump Idler Pulley | 1 |
| EB15009 | 07/05/2015 | Coaltram Service Sheets | 1 |
| EB15010 | 25/05/2015 | Removal of Level indicator Lights from Scrubber Level Sensors | 1 |
| EB15011 | 01/06/2015 | CT08 Boom Top Reinforcing Plate | 1 |
| EB15012 | 20/06/2015 | Coolant Loss and Engine Oil Pressure Test Tap | 1 |
| EB15014 | 28/07/2015 | Float Sensor Shaft Upgrade | 1 |
| EB15015 | 03/09/2015 | Nickel Plated ExDES Components | 1 |
| EB15016 | 28/10/2015 | MONEx Scrubber Floats | 1 |
| EB15017 | 11/11/2015 | C7 Engine Timing Sensor | 1 |
| EB15018 | 20/11/2015 | Coaltram Service Sheets | 1 |
| EB16001 | 14/04/2016 | CT08-CT10LP Boom Stiffening Upgrade | 1 |
| EB16002 | 14/04/2016 | MONEx Battery Overhaul | 1 |
| EB16003 | 14/04/2016 | MONEx Display Overhaul | 1 |
| EB16004 | 22/09/2016 | Service Life of MONEx Equipment | 1 |
| EB16005 | 05/09/2016 | Data Logger for FLP1 Throttle Watchdog System | 1 |
| EB16006 | 19/12/2016 | Spring Washers for Driveline | 1 |
| EB17001 | 21/02/2017 | COALTRAM Service Sheets | 1 |
| EB17002 | 26/04/2017 | CT08-CT10LP Lift Cylinder Anchor Point | 1 |
| EB17003 | 05/05/2017 | COALTRAM Rear Tow Hitch Allowable Vertical Load | 1 |
| EB17005 | 30/06/2017 | COALTRAM® Ex Equipment Compatibility List | 1 |
| EB17006 | 30/06/2017 | COALTRAM® Ex Compliance Audit | 1 |
| EB18003 | 21/06/2018 | MONEx Piezo Actuated Valve Parts Consolidation | 1 |
| EB18005 | 23/10/2018 | Exhaust Conditioner Level Float Update | 3 |
| EB18006 | 27/11/2018 | TBS Brake Pedal Update | 1 |
| EB20001 | 23/01/2020 | COALTRAM QDS Lock Cylinder Circuit | 1 |
| EB20003 | 03/07/2020 | COALTRAM Service Sheets Update | 1 |
| EB20004 | 29/07/2020 | COALTRAM Electrical Cable Protection Sleeves | 1 |
| EB23001 | 24/02/2023 | COALTRAM Service Sheets Update | 1 |
| EB24001 | 23/08/2024 | COALTRAM Service Sheets Update | 1 |

| Technical Bulletins | | | |
|---------------------|------------|--|-------|
| Doc # | Date | Description | Rev # |
| TBSA-0502 | 28/02/2008 | CT10 - Check Brake Wear | 1 |
| CTTB-11-001 | 02/12/2011 | Stick Steering Lever Mechanical Stops on Atlas Copco Coaltram Utility Vehicles | 1 |
| TB12001 | 16/11/2012 | Exhaust Leak at the Exhaust Conditioner to Exhaust Pipe Fixed Joint | 1 |
| TB13001 | 21/10/2013 | Park Brake Valve – Failure to Apply | 1 |
| TB13002 | 21/10/2013 | Exhaust Gas Test Port | 1 |
| TB13003 | 19/11/2013 | Isolation Air Reservoir and Check Valve | 1 |
| TB14001 | 20/05/2014 | HEP Solenoid | 1 |
| TB14002 | 03/07/2014 | Throttle Sensor | 1 |
| TB15001 | 12/03/2015 | Accelerator to display software upgrade | 1 |
| TB15002 | 12/03/2015 | Accelerator pedal position mechanical upgrade | 1 |
| TB15003 | 12/03/2015 | Accelerator pedal position - Hardware upgrade | 1 |
| TB15004 | 06/05/2015 | Throttle Pedal Cover | 1 |
| TB15005 | 20/10/2015 | Turbo Impacting on Methane Junction Box | 1 |
| TB15006 | 11/11/2015 | Park Brake Valve Scheduled Replacement | 1 |
| TB15007 | 21/12/2015 | Brake Pedal Piston Pin Retaining Clips | 1 |
| TB15008 | 21/12/2015 | Throttle Pedal Spring | 1 |
| TB16001 | 08/03/2016 | Crowd cylinder Gland Bush Bolt Failure | 1 |
| TB17001 | 10/02/2017 | HA108 Footswitch Enclosure | 1 |
| TB17002 | 22/08/2017 | Steer circuit pressure filter | 1 |
| TB17003 | 29/08/2017 | COALTRAM® Critical Components | 1 |

| Safety Bulletins | | | |
|------------------|------------|---|-------|
| Doc # | Date | Description | Rev # |
| SB13001 | 4/04/2013 | Transmission cover not latched securely leading to injury | 1 |
| SB14001 | 16/05/2014 | Oil ingress into ECUEx | 1 |
| SB14002 | 30/05/2014 | Cap screw failures | 1 |
| SB15001 | 9/01/2015 | Methane Air safety solenoid | 1 |
| SB15002 | 11/02/2015 | Steer Amplifier Valve | 1 |
| SB15003 | 9/03/2015 | Erratic Accelerator Operation | 1 |
| SB15004 | 9/03/2015 | Engine Cranking | 1 |
| SB15005 | 4/05/2015 | Uninitiated Engine Speed (Final Document) | 1 |
| SB19002 | 10/09/2019 | Jel Seat Dampener Failures | 1 |
| SB20001 | 14/08/2020 | Non-conforming Fuel Shutdown Cylinders | 1 |
| SB23001 | 16/08/2023 | COALTRAM CT08/CT10LP Crowd Cylinder Failures | 2 |

| Safety Alerts | | | |
|---------------|-----------|---|-------|
| Doc # | Date | Description | Rev # |
| SA17001 | 1/07/2017 | Potential concerns regarding NTMS Methane Systems | 1 |