

EB (Engineering Bulletins)

Doc #	Date	Description	Rev #
EB24002	03/12/2024	Driftrunner Service sheets Updated	1

GEN (General)

Doc #	Date	Description	Rev #
GEN2008-TBSA-02	27/10/2008	Driftrunner Select Valve	0
GEN2009-TBSA-01	23/03/2009	ALL Machines Fan Hub Failure	0
GEN2009-TBSA-03	04/06/2009	ALL Machines Possible Oil Injection Occurrence	0
GEN2010-TBSA-01	08/04/2011	Driftrunner Refurbished Steering Arm Failure	1
GEN2010-TBSA-02	9/09/2014	OEM Component Use	1
GEN2011-TBSA-01	18/03/2011	Driftrunner Explosion of Axle Tie Rod Assembly due to Heating	0
GEN2011-TBSA-03	07/06/2011	Brumby QICS Inspection	0
GEN2012-TBSA-01	18/06/2013	Driftrunner & Brumby Start Circuit Modification	0
GEN2012-TBSA-02	24/07/2012	Driftrunner Steering Valve Installation	0
GEN2012-TBSA-03	07/11/2012	Setco CSE Ex d Junction Box	0
GEN2013-TBSA-01	15/03/2013	Driftrunner F and G Series Service Sheets	0
GEN2014-TBSA-01	11/09/2014	Pneumatic Circuit Air Reservoir Product Improvement	0
GEN2015-TBSA-01	01/05/2015	Water Make Up Tank Filler Neck Product Improvement	0
GEN2016-TBSA-01	18/07/2016	Driftrunner F and G Series Bonnets	0

DES (Diesel Engine System)

Doc #	Date	Description	Rev #
DES2007-TBSA-02	01/10/2007	Driftrunner Brumby Pressure Regulator	0
DES2008-TBSA-01	04/09/2008	Driftrunner Brumby Possible Engine Shutdown Cylinder Failure	0
DES2009-TBSA-03	12/11/2012	Driftrunner Brumby Inlet Flametrap Alteration Expired	2
DES2009-TBSA-04	11/12/2009	Driftrunner Brumby Exhaust Particulate Filter Assembly Service	0
DES2011-TBSA-02	15/05/2011	Driftrunner Coolant Loss Valve	0
DES2011-TBSA-03	07/06/2011	Driftrunner Brumby MDA DES 13017 Part Number Updates	1
DES2011-TBSA-04	20/05/2011	Driftrunner Brumby MDA DES 13017 Exhaust Flamepath Joint Failure	0
DES2011-TBSA-05	02/06/2011	Driftrunner Brumby MDR090376DES Exhaust System Incident Notification	0
DES2011-TBSA-07	03/11/2011	MDA DES 13017 Purifier Bolt	0
DES2012-TBSA-01	29/02/2012	Driftrunner Brumby Fuel Pumps	0
DES2012-TBSA-02	18/04/2013	Fuel Shut Off Cylinder	2
DES2012-TBSA-04	31/05/2013	Driftrunner Brumby MDR090376DES Exhaust System Incident Notification	1
DES2014-TBSA-01	11/09/2014	MDR090376DES Design Registration Renewal	0
DES2014-TBSA-06	05/12/2014	MDA DES 13017 Component Flamepath Drawings	0
DES2016-TBSA-01	30/09/2016	MDR090376 Upgrade Strangler Valve	0
DES2017-TBSA-01	28/06/2017	MDR090376 Fasteners Inlet Flametrap Housing	0
DES2017-TBSA-02	17/08/2017	MDR090376 Intake Flametrap Housing Dimensional Tolerances	0
DES2017-TBSA-03	17/02/2020	DES Control Systems - Safety Critical Components	1
DES2018-TBSA-01	10/01/2018	MDR090736 Intake Flametrap Element and Housing Fixed Joint	0
DES2018-TBSA-02	10/01/2018	MDR090736 Thermal Sensor Valves (optional alternative)	0

GEN (General)

Doc #	Date	Description	Rev #
TBS2008-TBSA-03	29/12/2008	Driftrunner Oil Additive for Dana Spicer Arco 111 and 211 Axles	0
TBS2009-TBSA-01	26/03/2009	Driftrunner Brumby Ranger Service Brake Failed to Operate	0
TBS2010-TBSA-01	31/03/2010	Driftrunner Transport Braking System (211111 Axles)	0
TBS2010-TBSA-02	17/11/2010	Driftrunner, Brumby and Ranger Brake Pedal Assembly Modification	3
TBS2011-TBSA-01	16/11/2011	Driftrunner Transport Braking System (211111 Axles)	0
TBS2011-TBSA-02	16/11/2011	Driftrunner Transport Braking System Service Brake Diaphragm	0
TBS2011-TBSA-03	16/11/2011	Driftrunner & Brumby Transport Braking Systems	0
TBS2012-TBSA-01	20/09/2012	Driftrunner & Brumby Master Cylinders Incident Notification	1
TBS2015-TBSA-01	10/04/2015	Driftrunner Axle - Steering Component Failure	0